

3D45 Firmware Version Number	Release Date	Changes
R02.11.17	June 17, 2021	<ul style="list-style-type: none"> • Non Dremel Filament UI • PLA. ECO-ABS bed temperature improvements
R02.10.09	September 23, 2020	<ul style="list-style-type: none"> • 3DPrinterOS print cloud for EU countries and user (NA unchanged) • Bug fix for rare intermittent pausing during print
R02.09.04	February 17, 2020	<ul style="list-style-type: none"> • Greek language support added • Polish language support added • Portuguese language support added • Turkish language support added • Fixed: PETG Platform temperature range • Fixed: Various languages issues • Fixed: Assisted Nozzle Calibration - rectangles not printed in correct order • Fixed: Sound level and helpful hints are not cleared after a factory reset • Fixed: Hot keys name does not update after restoring defaults
R02.08.08	October 28, 2019	<ul style="list-style-type: none"> • Fixed: Prints occasionally would not finish last layer • Various security improvements
R02.07.04	August 19, 2019	<ul style="list-style-type: none"> • Russian language support added • Hungarian language support added • Security improvement with Polar 3D Cloud connection
R02.05.03	March 15, 2019	<ul style="list-style-type: none"> • Fixed: Random pausing during printing • Fixed: Ensure build platform moves to home position after print completion
R02.04.31	February 22, 2019	<ul style="list-style-type: none"> • Fixed: Dremel DigiLab 3D Slicer network communication causing printer software freezing • Auto-calibration (leveling) feature added • Polar 3D Cloud support for Australia added • Polar 3D Cloud support for New Zealand added • Disable object fan cooling on first layer • Reduce servo motor touch-off speed during leveling